



More information about Artec Ray II Visit our knowledge base (kennisbank)






# Introduction

In this document you will find the method to use the multicharger for charging the batteries for your Ray II scanner.



# **Charger Components**




## **Description of the system**

## **Supported batteries**




## **Power Supply**



#### **Charging function/Calibration function**




## **Charging times**





## **Charging Function**


## Inserting and charging the batteries




## **Charging priority**








### **Change of charging priority**




#### **Calibration Function**

## Option 1


## Charger recommends a calibration






# Option 2


## Request a calibration




#### **Calibration Function**



#### **Error Indication**



# **Troubleshooting**



Have fun scanning with **ARTEC RAY II** 





# **4C Creative Cad Cam Consultants**

4C Creative CAD CAM Consultants is a company specialized in 3D technologies and is located in Emmen, Drenthe. 4C is your partner for delivering professional hardware and software for 3D scanning, reverse engineering, AR & VR and quality control.

#### Contact



info@4cccc.nl



+31 (0)591 - 377 442

For more information, FAQ, updates, documents and videos about Artec Ray II go to 4cccc.nl/kennisbank/artec-ray-2

